


**0400-TF160-R000K0-5S01**

Machine: TSUGAMI

Type: B386 II

Emplacement, N°: Front back gang tool post


Travail sur: Broche principale


Type de travail: n<sub>max</sub>: -i (n<sub>i</sub> / n<sub>o</sub>): -


Attachement: 4x 16x16 + 1x 20x20 (4x 5/8"x5/8" + 1x 3/4"x3/4")


Sans refroidissement


Infos:


**0400-TF160-R000K0-5S01**

Machine: TSUGAMI  
Type: B386 II  
Location, N°: Front back gang tool post  
Work on: Main spindle  
Type of work:   
n<sub>max</sub>: -  
i (n<sub>i</sub> / n<sub>0</sub>): -  
Attachement: 4x 16x16 + 1x 20x20 (4x 5/8"x5/8" + 1x 3/4"x3/4")  
Without coolant  
Infos:

**0400-TF160-R000K0-5S01**

Maschine: TSUGAMI  
Typ: B386 II  
Position, N°: Front back gang tool post  
Arbeit über: Hauptspindel  
Arbeitstyp:   
n<sub>max</sub>: -  
i (n<sub>i</sub> / n<sub>o</sub>): -  
Befestigung: 4x 16x16 + 1x 20x20 (4x 5/8"x5/8" + 1x 3/4"x3/4")  
Ohne Kühlmittel  
Infos:

**0400-TF160-R000K0-5S01**

Macchina: TSUGAMI  
Tipo: B386 II  
Posizione, N°: Front back gang tool post  
Lavoro al: Mandrino principale  
Tipo di lavoro:   
n<sub>max</sub>: -  
i (n<sub>i</sub> / n<sub>o</sub>): -  
Ataccamento: 4x 16x16 + 1x 20x20 (4x 5/8"x5/8" + 1x 3/4"x3/4")  
Senza refrigerante  
Informazioni: