


**GDF1110**




Machine: CITIZEN

Type: L20E-1M7 / L20E-1M8 / L20E-1M9 / L20X

Emplacement, N°: Upper gang tool post

Travail sur: Broche principale


Type de travail: 


Attachement: 3x  $\varnothing 19.05$


Sans refroidissement


Infos:

**GDF1110**



Machine: CITIZEN  
Type: L20E-1M7 / L20E-1M8 / L20E-1M9 / L20X  
Location, N°: Upper gang tool post  
Work on: Main spindle  
Type of work:   
Attachement: 3x  $\varnothing 19.05$   
Without coolant  
Infos:

**GDF1110**

Maschine: CITIZEN  
Typ: L20E-1M7 / L20E-1M8 / L20E-1M9 / L20X  
Position, N°: Upper gang tool post  
Arbeit über: Hauptspindel  
Arbeitstyp:   
Befestigung: 3x  $\varnothing 19.05$   
Ohne Kühlmittel  
Infos: